

Report for the Labour-Management Network September 2025

Monthly Statistics

Reporting Month	Fatalities	Critical Injuries	Total
June 1 – July 31, 2025	1	79	80
June 1 – July 31, 2024	2	61	63

Fatality & Critical Injury Year-to-Date Overview – Construction

Reporting Months	Fatalities	Critical Injuries	Total
Jan. 1 – July 31, 2025	7	210	217
Jan. 1 – July 31, 2024	6	177	183

Helping you achieve compliance on construction projects and window cleaning operations

[General requirements](#)

[Access to and egress from a work area](#)

[Excavations](#)

[Fall protection and roofing re-shoring](#)

[Equipment](#)

[Electrical hazards](#)

[Hygiene](#)

[Forms, formwork, falsework, and](#)

[Housekeeping, fire protection, public way protection, traffic control, and hot tar or bitumen tankers or kettles](#)

[Asbestos on construction projects](#)

[Diving operations](#)

[Window cleaning operations](#)

[Workplace Hazard Alerts | Ontario.ca](#)

Disclaimer: This information has been prepared to assist workplace parties in understanding their rights and duties under the Occupational Health and Safety Act (OHSA) and its regulations. This information does not constitute legal advice. To determine your rights and duties under the OHSA, please contact your legal counsel or refer to the legislation.

Section 1 – Senior Manager's Comment

It's well understood by those familiar with the sector that falls from heights—whether from equipment, ladders, or elevated surfaces—remain a leading cause of critical and fatal injuries in construction. This is especially true on single-family and multi-family residential projects across Ontario.

Between January 2015 and December 2024, 97 fatalities were directly attributed to falls. This represents **75.78%** of all construction-related fatalities during that period—a sobering statistic that underscores the ongoing risks associated with working at heights.

Although over 1.4 million individuals have completed training through an approved Working at Heights (WAH) provider, we continue to observe concerning trends in the field:

1. Workers may not consistently use fall protection equipment correctly—or at all.
2. Supervisors may not always enforce the proper use of fall protection measures.
3. Employers may fall short in ensuring that both workers and supervisors fulfill their responsibilities under the OHSA and its regulations.
4. Constructors may not be holding employers, supervisors, or workers accountable for compliance with working at heights requirements.
5. Often, these issues arise from a combination of the above factors.

To help address these challenges, beginning September 1, 2025, Senior Training Standards Assessors from our Prevention Office will be joining East Region inspectors on-site as part of our ongoing campaign focused on the residential construction sector. Their involvement will serve two key purposes:

1. To support quality assurance and control efforts by evaluating the effectiveness of WAH training and determining whether the knowledge gained is being applied in practice.
2. To verify the authenticity of WAH training cards and identify any that may be fraudulent. Where issues are identified, inspectors will take appropriate enforcement action.



Sincerely, Francois Malette

A/Senior Manager
Construction Health and Safety Program
Occupational Health and Safety Branch
Ontario Ministry of Labour, Training and Skills Development

Section 2 – What's New

Protecting workers across Ontario

The Ontario government has launched the sixth round of the Skills Development Fund (SDF) Training Stream. This round will provide \$260 million for innovative projects that support the hiring, training and upskilling of workers in manufacturing, health care, construction, automotive and other skilled trades.

Recent announcements about Skills Development Fund (SDF) investments in regions across the province include:

- [Over \\$4 million](#) through the SDF Training Stream to help nearly 500 people in Thunder Bay and surrounding areas find good-paying jobs in the construction, industrial, mining and transportation sectors.
- [Over \\$13 million](#) through the SDF Training and Capital Streams to help over 1,000 workers and jobseekers in Sudbury and surrounding areas prepare for in-demand jobs in boilermaking, welding, mining and ironworking sectors.
- [More than \\$2.8 million](#) through the SDF Training Stream to help people in Durham Region and surrounding areas find good-paying jobs in the construction, manufacturing and skilled trades sectors.
- [More than \\$5 million](#) through the SDF Training Stream to help more than 2,900 youth, jobseekers and apprentices across Northumberland and Peterborough areas prepare for careers in high-demand sectors such as construction, manufacturing, motive power and aviation.

For the latest what's **new** – MLITSD articles, see: [What's New!](#)

Section 3 – Court Bulletins

Workplace Fatality Results in \$115,000 Fine for Ottawa-based Company

Convicted: 769550 Ontario Ltd. operating as Ottawa Pavemaster, 240 Cowley Avenue, Ottawa, Ontario, a construction company that performs asphalt paving.

Location of Workplace: 93 to 107 Desmond Avenue, Kanata, Ontario.

Description of Offence: A worker was fatally injured by a truck that was backing up. The company failed to ensure the driver of the truck was assisted by a signaller contrary to [Section 104\(3\) of Ontario Regulation 213/91](#), an offence under [Section 66\(1\)](#) of the *Occupational Health and Safety Act*. [Section 25\(1\)\(c\)](#) of the Act states that “an employer shall ensure, that the measures and procedures prescribed are carried out in the workplace.”

Date of Offence: August 15, 2023

Date of Conviction: June 26, 2025

Penalty Imposed:

- Following a guilty plea in Provincial Offences Court, Ottawa, Ottawa Pavemaster was fined \$115,000 by Justice of the Peace Harley Gervais; Crown Counsel was Alicia Gordon-Fagan.
- The court also imposed a 25 per cent victim fine surcharge as required by the *Provincial Offences Act*. The surcharge is credited to a special provincial government fund to assist victims of crime.

Background:

- On the day of the incident, Ottawa Pavemaster was completing a driveway paving job.
- A company worker engaged in the project was walking along Desmond Avenue when he was fatally injured by a reversing dump truck.

- The truck was driven by a company employee who was backing up approximately 200 feet to connect to a float, a trailer used to haul drivable equipment.
- The driver was reversing the truck without the assistance of a signaller, another worker who would watch and alert on possible hazards. This led to the first worker being fatally struck.

Court Bulletins can be found here: <https://news.ontario.ca/en>

Considerations from a Root Cause point of view:


- *The facts of the case indicate that the driver was reversing to hook up the trailer to haul equipment, suggesting that the work was complete for the day.*
 - *Did the timing play a factor?*
 - *Was the packing up of equipment and preparing to leave not considered as part of the work to be completed?*
 - *Was the movement of equipment despite the 'task' being completed not considered to remain a hazard?*
- *Did the layout of the project play a factor?*
 - *Why would the driver need to reverse on a project, particularly a stretch of 200 feet?*
 - *If the layout of the project was such that reversing was necessary, did the driver or supervisor not recognize the need or requirement for a signaller?*

This highlights the importance of remaining vigilant and consistently applying hazard controls until all job activities are fully completed. Regulatory requirements apply throughout the entire project—not only during high-risk tasks. Unfortunately, we are seeing a rise in incidents occurring during routine or transitional activities, where risk awareness may be diminished.

Section 4 – Enforcement Trends – June / July 2025

MLITSD Construction Inspectors conducted **3,913** field visits during the months of June and July 2025 resulting in **8,493** orders and requirements, which includes **732** Stop Work Orders accompanied by **1,788** Time Unknown Orders.

Of the total number of field visits, Construction Inspectors responded **942** initial events, with **480** follow up visits. The breakdown of initial events is as follows:



2025 – 2026 Campaign


June / July 2025

Field Visits


Workplace Sector	Field Visits
Single Family Housing	762
Residential Building Construction	237
Apartment & Other Multiple Housing	157
Low-Rise (less than 4 storeys)	87
High-Rise (10 storeys or more)	47
Medium-Rise (4 to 9 storeys)	21
Total	1,334


Contravention	Orders	
Fall Protection	878	
PPE (excluding fall protection)	765	
Ladders	347	
Scaffold	287	
Stairs and Landings	282	
Emergency Management	204	
Equipment, General	160	
Access and Egress	150	
Fire Safety	142	
Housekeeping	142	
Hygiene	118	
SUB-TOTAL	3,475	78.8%
All other sections (incl. 5 & 6)	934	21.2%
TOTAL	4,409	100.0%

Complaints by Sector - June/July 2025



Injuries / Incidents by Sector - June/July 2025





Ministry of Labour, Immigration, Training and Skills Development Occupational Health and Safety Branch, Construction Health and Safety Program



Section 5 – Critical Injuries & Fatalities

Year-to-Date Overview and Comparison - Construction Sector

Injury Type	2025 June / July		2025 January 1 – July 31
Critical	41	38	210

Injury Type	2024 June / July		2024 January 1 – July 31
Critical	27	34	216

NOTE: These figures represent preliminary data and are not to be considered official statistics from the Ministry of Labour, Immigration, Training and Skills Development. Official statistics will be issued quarterly by the Program Analysis, Evaluation and Outcomes Unit of the Occupational Health and Safety Branch of the Ministry of Labour, Immigration, Training and Skills Development. Data are subject to change due to updates in the enforcement database. Only events reported to the ministry are included here. Except for fatalities, event categories in the ministry's data set are based on what was assigned at the time of the initial report to the ministry. The reported event category may not represent what occurred at the workplace.

Critical Injuries – June / July 2025

June/July 2025 CRITICALS	RESS	INST	RESM	INDU	ROAD	COMM	NECC	RAIL	ETTL	HYDR	SEWW	PAVE	TOTAL
Falls from Heights	4	1	4	1									10
Falls From Equipment	2	4	4						1			1	12
Falls from Ladders	1	3	1										5
Same level slips and trips	5		8	3	2		1						19
Struck by equipment			1				1				1		3
Struck by material	1		5	1			1	1			1		10
Excavation Collapse			1										1
Other, including multiple factors, i.e. fall resulting from scaffold being struck by equipment.	2	2	5	1	1	1		1		1	3	2	19
TOTAL	15	10	29	6	3	3	2	1	1	2	4	3	79

NOTE: To make this chart more reader friendly, columns and rows where the values are '0' have been removed.

Critical Injuries - Year to Date 2025

YTD 2025 CRITICALS	RESS	INST	RESM	INDU	ROAD	EXCA	COMM	NECC	RAIL	POWP	ETTL	HYDR	SEWW	BRID	MARE	PAVE	GAS	CAIS	TOTAL
Falls from Heights	10	1	4	2				1											18
Falls From Equipment	3	8	10	2	1			1			1	1				1			28
Falls from Ladders	5	5	8	2				7										1	28
Same level slips and trips	10	4	17	8	2			4	4	1	1	1	1	1	1	1		2	58
Struck by equipment		1	4	2				2	2				1						12
Struck by material	3	1	10	2				3	1				1	2	1				24
Electrical Contact								1			1								2
Excavation Collapse			1																1
Other, including multiple factors, i.e. fall resulting from scaffold being struck by equipment.	5	3	12	3	1	2	4		1	1		2	3			2			39
TOTAL	36	23	66	21	4	2	23	7	2	2	3	4	7	2	1	3	3	1	210

NOTE: To make this chart more reader friendly, columns and rows where the values are '0' have been removed.

Ministry of Labour, Immigration, Training and Skills Development
Occupational Health and Safety Branch, Construction Health and Safety Program



	Date of Incident	Municipality	Sector	Occupation	Details (As reported to MLITSD)	Reported Cause
1	June 2, 2025	Toronto	Residential Building Construction	Rofer	Worker suffered fractured wrist after falling from a ladder that two other workers were also on.	Fall – From Ladder
2	June 2, 2025	Toronto	Apartment & Other Multiple Housing	Labourer	Worker suffered critical injuries after the walls of a trench collapsed, trapping him.	Excavation - Collapse
3	June 2, 2025	Ottawa	Apartment & Other Multiple Housing	Framer	Worker suffered loss of blood and life-threatening injuries after falling from the second storey of a structure.	Fall – From Height
4	June 3, 2025	Aurora	Asphalt Paving	Operator	Worker suffered a broken foot after being thrown from the resurfacing equipment.	Fall – From Equipment
5	June 3, 2025	Brampton	Institutional Building Construction	Operator	Worker suffered a fractured ankle after stepping out of the bobcat.	Fall – From Equipment
6	June 3, 2025	Amherstview	Institutional Building Construction	HVAC Technician	Worker suffered a broken wrist after falling from a ladder.	Fall – From Ladder

Ministry of Labour, Immigration, Training and Skills Development
Occupational Health and Safety Branch, Construction Health and Safety Program



	Date of Incident	Municipality	Sector	Occupation	Details (As reported to MLITSD)	Reported Cause
7	June 3, 2025	Orleans	Single Family Housing	Insulator	Worker suffered a broken leg after falling down a set of stairs.	Fall – Same Level
8	June 4, 2025	Toronto	Sewer/Watermain Construction	Pipefitter	Worker suffered a fracture to his wrist after being struck by equipment being lifted from an excavation.	Struck by - Equipment
9	June 4, 2025	Ajax	Institutional Building Construction	Sheet Metal Worker	Worker suffered multiple fractures in one arm after falling from a ladder.	Fall – From Ladders
10	June 5, 2025	Cassleman	Single Family Housing	Rofer	Worker suffered a broken arm after tripping while walking on the driveway.	Fall – Same Level
11	June 5, 2025	Toronto	Apartment & Other Multiple Housing	Carpenter	Worker fractured his ankle after tripping over a 4x4.	Fall – Same Level
12	June 5, 2025	Niagara Falls	Institutional Building Construction	Carpenter	Worker suffered a critical injury to his arm after falling from a ladder.	Fall – From Ladder

Ministry of Labour, Immigration, Training and Skills Development
Occupational Health and Safety Branch, Construction Health and Safety Program



	Date of Incident	Municipality	Sector	Occupation	Details (As reported to MLITSD)	Reported Cause
13	June 10, 2025	New Liskeard	NEC - Construction	Worker	Worker broken his arm after climbing over a concrete barrier, falling over the back side.	Fall – Same Level
14	June 11, 2025	Toronto	Single Family Housing	Welder	Worker suffered fractured ankle after fell from a platform.	Fall – From Equipment
15	June 12, 2025	Pickering	Industrial Building Construction	Sound Technician	Worker suffered a broken leg when his scissor lift tipped, causing the unit and worker to fall to the ground.	NEC - Construction
16	June 12, 2025	Thornhill	Residential Building Construction	Painter	Workers suffered fractures to both feet after falling from a ladder.	Fall – From Ladder
17	June 12, 2025	Kitchener	Institutional Building Construction	Rofer	Worker suffered a broken arm after falling over the edge to the ground while removing a bump line.	Fall – From Heights
18	June 13, 2025	Scarborough	Apartment & Other Multiple Housing	Worker	Worker fell while walking down a small incline, resulting in a broken ankle.	Fall – Same Level

Ministry of Labour, Immigration, Training and Skills Development
Occupational Health and Safety Branch, Construction Health and Safety Program



	Date of Incident	Municipality	Sector	Occupation	Details (As reported to MLITSD)	Reported Cause
19	June 13, 2025	King City	Sewer/Watermain Construction	Labourer	Worker was struck in the head by the bucket of an excavator, resulting in a loss of consciousness.	NEC - Construction
20	June 13, 2025	Brampton	Apartment & Other Multiple Housing	Plumber	Worker suffered a broken leg after falling from a second storey balcony.	Fall – From Height
21	June 13, 2025	Kitchener	Apartment & Other Multiple Housing	Labourer	Worker suffered a broken leg after tripping over debris.	Fall – Same Level
22	June 14, 2025	Toronto	Commercial Building Construction	Worker	Worker lost consciousness after being assaulted by another worker.	NEC - Construction
23	June 14, 2025	Kettleby	Single Family Housing	Sheet Metal Worker	Worker suffered life threatening injuries after falling into an elevator shaft.	Fall – From Height
24	June 14, 2025	Hamilton	Apartment & Other Multiple Housing	Rigger	Worker lost consciousness after being struck by the load being lowered.	Struck by - Material

Ministry of Labour, Immigration, Training and Skills Development
Occupational Health and Safety Branch, Construction Health and Safety Program



	Date of Incident	Municipality	Sector	Occupation	Details (As reported to MLITSD)	Reported Cause
25	June 14, 2025	Leamington	Commercial Building Construction	Glazer	Worker suffered a broken leg when his scissor lift tipped, causing the unit and worker to fall to the ground.	NEC - Construction
26	June 16, 2025	London	Commercial Building Construction	Mason	Worker suffered multiple fractures to his leg after a forklift struck the scaffold he was on, resulting in a fall.	Fall – From Equipment
27	June 17, 2025	Etobicoke	Apartment & Other Multiple Housing	Worker	Worker suffered critical injury after being struck in the head by chain pulley broke, striking the worker.	Struck by - Equipment
28	June 17, 2025	Ottawa	Highway & Road Construction	Technician	Worker suffered a broken ankle after tripping and falling.	Fall – Same Level
29	June 17, 2025	Milton	Single Family Housing	Electrician	Worker lost consciousness after receiving a large laceration to his arm.	NEC - Construction
30	June 18, 2025	Cornwall	Commercial Building Construction	Landscaper	Worker suffered significant loss of	NEC - Construction

Ministry of Labour, Immigration, Training and Skills Development
Occupational Health and Safety Branch, Construction Health and Safety Program



	Date of Incident	Municipality	Sector	Occupation	Details (As reported to MLITSD)	Reported Cause
					blood after being cut by chain saw.	
31	June 19, 2025	Toronto	Asphalt Paving	Operator	Worker suffered fractures to his foot after it became entangled in a machine in motion.	NEC - Construction
32	June 19, 2025	Etobicoke	Apartment & Other Multiple Housing	Operator	Worker suffered critical injuries after a load let loose, crashing through the glass of the cab.	Struck by - Material
33	June 20, 2025	Grimsby	Single Family Housing	Iron Worker	Worker suffered loss of consciousness after being struck by an I-Beam.	Struck by - Material
34	June 21, 2025	Burlington	Single Family Housing	Rofer	Worker suffered critical injury after falling from a roof.	Fall – From Height
35	June 23, 2025	Toronto	Apartment & Other Multiple Housing	Worker	Worker suffered fracture to his shoulder after falling in the bed of his pick-up truck.	Fall – Same Level

Ministry of Labour, Immigration, Training and Skills Development
Occupational Health and Safety Branch, Construction Health and Safety Program



	Date of Incident	Municipality	Sector	Occupation	Details (As reported to MLITSD)	Reported Cause
36	June 23, 2025	Toronto	Single Family Housing	Rofer	Worker lost consciousness after falling from the roof to the ground.	Fall – From Height
37	June 23, 2025	Toronto	Commercial Building Construction	Worker	Worker lost footing on stairs and fell, resulting in a fractured wrist.	Fall – Same Level
38	June 24, 2025	Ottawa	Sewer/Watermain Construction	Utility Worker	Worker was struck by the scoop of an excavator, resulting in a loss of consciousness.	NEC - Construction
39	June 25, 2025	Windsor	Industrial Building Construction	Building Inspector	Worker tripped over barriers, resulting in a broken arm.	Fall – Same Level
40	June 27, 2025	Tillsonburg	Industrial Building Construction	Iron Worker	Worker sustained critical injury to both legs after being pinned by a steel column being moved by a crane.	Struck by - Material
41	June 30, 2025	Toronto	Apartment & Other Multiple Housing	Drywaller	Worker suffered critical injury after falling while descending scaffold.	Fall – From Equipment

Ministry of Labour, Immigration, Training and Skills Development
Occupational Health and Safety Branch, Construction Health and Safety Program



	Date of Incident	Municipality	Sector	Occupation	Details (As reported to MLITSD)	Reported Cause
42	July 3, 2025	Pickering	Single Family Housing	Labourer	Worker suffered a fractured elbow after slipping while securing material on a truck.	Fall – Same Level
43	July 3, 2025	Nepean	Commercial Building Construction	Signaller	Worker was struck by a front-end loader when the operator left the controls unattended.	Struck by - Equipment
44	July 4, 2025	Ottawa	Apartment & Other Multiple Housing	Worker	Worker suffered a broken arm after tripping and falling.	Fall – Same Level
45	July 5, 2025	Wallaceburg	Apartment & Other Multiple Housing	Rofer	Worker suffered critical injuries after falling from the roof.	Fall – From Height
46	July 7, 2025	Kanata	Apartment & Other Multiple Housing	Operator	Worker slipped and fell from the truck resulting in a critical injury.	Fall – From Equipment
47	July 7, 2025	Windsor	Single Family Housing	Worker	Worker lost footing on the stairs, leading to a fall resulting in a fractured ankle.	Fall – Same Level
48	July 8, 2025	Brighton	Single Family Housing	Operator	Worker suffered life threatening injuries when he	NEC - Construction

Ministry of Labour, Immigration, Training and Skills Development
Occupational Health and Safety Branch, Construction Health and Safety Program



	Date of Incident	Municipality	Sector	Occupation	Details (As reported to MLITSD)	Reported Cause
					was ejected from the boom truck when it rolled into an excavation.	
49	July 8, 2025	Ottawa	Institutional Building Construction	Operator	Worker suffered fractured arm when he was ejected from the skid steer.	NEC - Construction
50	July 9, 2025	East Gwillimbury	Sewer/Watermain Construction	Dump Truck Operator	Worker suffered multiple critical and life-threatening injuries after a motor vehicle incident.	NEC - Construction
51	July 9, 2025	Brampton	Single Family Housing	Mason	Worker suffered a broken ankle after falling from a scaffold.	Fall – From Equipment
52	July 10, 2025	Toronto	Institutional Building Construction	Mason	Worker suffered a broken leg and head injuries after falling from a scaffold.	Fall – From Equipment
53	July 10, 2025	Mississauga	Industrial Building Construction	Concrete Worker	Worker suffered a broken wrist after tripping while laying re-bar.	Fall – Same Level
54	July 10, 2025	Oshawa	Asphalt Paving	Truck Driver	Worker suffered multiple critical and life-threatening	NEC - Construction

Ministry of Labour, Immigration, Training and Skills Development
Occupational Health and Safety Branch, Construction Health and Safety Program



	Date of Incident	Municipality	Sector	Occupation	Details (As reported to MLITSD)	Reported Cause
					injuries after a motor vehicle incident.	
55	July 11, 2025	Newmarket	Highway & Road Construction	Worker	Worker lost footing while loading the truck, leading to a fall resulting in a broken leg.	Fall – Same Level
56	July 14, 2025	Pickering	Institutional Building Construction	Painter	Worker suffered critical injury after falling from a scaffold.	Fall – From Equipment
57	July 14, 2025	Bowmanville	Hydro	Line Worker	Worker suffered fractures to both ankles after jumping off a concrete block.	NEC - Construction
58	July 15, 2025	Toronto	Apartment & Other Multiple Housing	Worker	Worker lost footing while descending site trailer stairs, resulting in a fractured ankle.	Fall – Same Level
59	July 17, 2025	East York	Single Family Housing	Supervisor	Worker lost footing while descending stairs, resulting in a fractured wrist.	Fall – Same Level
60	July 18, 2025	Petrolia	Railway	Maintenance Worker	Worker suffered a fractured foot when it became stuck in a tree	NEC - Construction

Ministry of Labour, Immigration, Training and Skills Development
Occupational Health and Safety Branch, Construction Health and Safety Program



	Date of Incident	Municipality	Sector	Occupation	Details (As reported to MLITSD)	Reported Cause
					root and the machine moved forward.	
61	July 21, 2025	Toronto	Apartment & Other Multiple Housing	Insulator	Worker suffered fractured left arm after falling from a ladder.	Fall – From Ladder
62	July 21, 2025	Toronto	Commercial Building Construction	Insulator	Worker suffered a fractured ankle after a wall frame lowered onto it.	Struck by - Material
63	July 21, 2025	Shelburne	Single Family Housing	Rofer	Worker suffered a broken ankle after falling from the roof.	Fall – From Height
64	July 21, 2025	Richmond Hill	Highway & Road Construction	Banksman	Worker suffered life threatening injuries after being struck by a vehicle.	Struck by - Vehicle
65	July 22, 2025	Toronto	Apartment & Other Multiple Housing	Drywaller	Worker suffered broken arm after falling from a scaffold.	Fall – From Equipment
66	July 22, 2025	Ottawa	Commercial Building Construction	Gas Technician	Worker suffered a loss of consciousness.	NEC - Construction
67	July 22, 2025	St. Catharines	Shipbuilding & Repair	Labourer	Worker suffered critical injuries when he was struck by a steel plate.	Struck by - Material

Ministry of Labour, Immigration, Training and Skills Development
Occupational Health and Safety Branch, Construction Health and Safety Program



	Date of Incident	Municipality	Sector	Occupation	Details (As reported to MLITSD)	Reported Cause
68	July 23, 2025	Mississauga	Industrial Building Construction	Roofer	Worker suffered broken leg and life-threatening injuries after falling through a hole in the roof.	Fall – From Height
69	July 23, 2025	Ottawa	Industrial Building Construction	Electrician	Worker suffered fractured ankle while walking backward and tripping.	Fall – Same Level
70	July 23, 2025	Kitchener	Institutional Building Construction	Mason	Worker suffered fractured shoulder after falling from a scaffold he was on while moving.	Fall – From Equipment
71	July 24, 2025	Bowmanville	Hydro	Worker	Worker suffered critical injuries after being struck by material that shift off a forklift.	Struck by - Material
72	July 25, 2025	Toronto	Apartment & Other Multiple Housing	Worker	Worker suffered a loss of consciousness.	NEC - Construction
73	July 25, 2025	Toronto	Apartment & Other Multiple Housing	Worker	Worker suffered a loss of consciousness.	NEC - Construction
74	July 27, 2025	Toronto	Sewer/Watermain Construction	Worker	Worker suffered a loss of consciousness.	NEC - Construction

Ministry of Labour, Immigration, Training and Skills Development
Occupational Health and Safety Branch, Construction Health and Safety Program



	Date of Incident	Municipality	Sector	Occupation	Details (As reported to MLITSD)	Reported Cause
75	July 28, 2025	Pickering	Apartment & Other Multiple Housing	Signaller	Worker suffered a fractured leg after being struck by the load of the crane.	Struck by - Material
76	July 28, 2025	Mississauga	Electrical Towers & Transmission Lines	Line Worker	Worker fractured both wrists after falling from a sky-jack.	Fall – From Equipment
77	July 28, 2025	Hamilton	Apartment & Other Multiple Housing	Electrician	Worker suffered a broken arm when the spindle let loose and struck him.	Struck by - Material
78	July 28, 2025	Guelph	Apartment & Other Multiple Housing	Roofer	Worker sustained lift threatening injuries after falling from a ladder while attempting to access the roof.	Fall – From Height
79	July 31, 2025	Waterdown	Institutional Building Construction	Labourer	Worker lost consciousness after suffering a small laceration.	NEC - Construction

Fatality Summary – June / July 2025

Injury Type	2025 June / July		2025 January 1 – July 31
Fatal	0	1	7

Injury Type	2024 June / July		2024 January 1 – July 31
Fatal	0	2	8

Fatalities – June / July 2025

June/July 2025 FATALS	RESS	TOTAL
Falls from Heights	1	1
TOTAL	1	1

NOTE: To make this chart more reader friendly, columns and rows where the values are '0' have been removed.

Fatalities – Year to Date 2025

YTD 2025 FATALS	RESS	RESM	NECC	HYDR	Total
Falls from Heights	2	1			3
Struck by equipment			1	1	2
Struck by material	1				1
Electrical Contact		1			1
TOTAL	3	2	1	1	7

NOTE: To make this chart more reader friendly, columns and rows where the values are '0' have been removed.

	Date of Incident	Municipality	Sector	Occupation	Details (As reported to MLITSD)	Reported Cause
7	July 3, 2025	Toronto	Single Family Housing	Rofer	Worker sustained fatal injuries after falling from height.	Fall – From Height
6	April 20, 2025	Ottawa	Single Family Housing	Foundation Cribbing and Installation	Workers sustained fatal injuries after	Struck by - Material

Ministry of Labour, Immigration, Training and Skills Development
Occupational Health and Safety Branch, Construction Health and Safety Program



	Date of Incident	Municipality	Sector	Occupation	Details (As reported to MLITSD)	Reported Cause
					being crushed by material	
5	March 19, 2025	Niagara Falls	Apartment and Other Multiple Housing	Rofer	Worker sustained fatal injuries when his aluminum ladder contacted an energized line while lowering the ladder	Electrocution
4	February 27, 2025	Kynoch	Hydro	Technician (59 Yrs. Old)	Worker sustained a fatal injury after being struck by bulldozer	Struck by - Equipment
3	February 3, 2025	Ottawa	Apartment and Other Multiple Housing	Labourer (32 Yrs. Old)	Worker fell through a floor opening, approx. 30ft, succumbing to his injuries	Fall – From Height
2	January 24, 2025	Goderich	NEC – Construction (Wind Turbine)	Crane Apprentice	Worker sustained fatal injuries after being struck by a skidsteer	Struck by - Equipment
1	January 6, 2025	Burlington	Single Family Housing	Rofer (Age:20)	Worker fell from a roof on Dec. 31, 2024, succumbing to his injuries on Jan. 6, 2025	Fall – From Height

SECTOR DESCRIPTION	SHORT DESC
Asbestos Removal - Type 1	ASB1
Asbestos Removal - Type 2	ASB2
Asbestos Removal - Type 3	ASB3
Bridge Construction	BRID
Cable	CABL
Caisson	CAIS
Cofferdam	COFF
Commercial Building Construction	COMM
Diving Construction	DCON
Diving Environmental	DENV
Diving Industrial	DIND
Diving Mining	DMIN
Electrical Towers & Transmission Lines	ETTL
Excavation	EXCA
Gas Service Connection	GAS
Excavation - Grading	GRAD
Hydro	HYDR
Industrial Building Construction	INDU
Institutional Building Construction	INST
Marine Construction	MARE
Mining Plant Construction	MINP
Moving of a Building/Structure	MOVE
NEC – Construction (NEC: not elsewhere captured)	NECC
NEC – Diving (NEC: not elsewhere captured)	NECD
Asphalt Paving	PAVE
Pipeline	PIPE
Hydroelectric Power Plants & Rel	POWP
Railway	RAIL
Apartment & Other Multiple Housing	RESM
Single Family Housing	RESS
Highway & Road Construction	ROAD
Sewer/Watermain Construction	SEWW
Shaft Construction	SHAF
Shipbuilding & Repair	SHIP
Subway	SUBW
Telephone	TELE
Trenching	TREN
Tunnel	TUNN
Well Drilling	WELL
Window Cleaning Services	WIND