

# Ministry of Labour, Immigration, Training and Skills Development

## Occupational Health and Safety Branch - Construction Health and Safety Program

### Report for the Labour-Management Network November 2025

#### Monthly Statistics

Reporting Month	Fatalities	Critical Injuries	Total
September 2025	1	45	46

#### Fatality & Critical Injury Overview

Reporting Months	Fatalities	Critical Injuries	Total
Year to Date 2025	8	285	293

Resources to help you achieve compliance on construction projects and window cleaning operations

[General requirements](#)

[Access to and egress from a work area](#)

[Asbestos on construction projects](#)

[Diving operations](#)

[Electrical hazards](#)

[Equipment](#)

[Excavations](#)

[Fall protection and roofing](#)

[Forms, formwork, falsework, and re-shoring](#)

[Housekeeping, fire protection, public way protection, traffic control, and hot tar or bitumen tankers or kettles](#)

[Hygiene](#)

[Window cleaning operations](#)

[Workplace Hazard Alerts | Ontario.ca](#)

**Disclaimer:** This information has been prepared to assist workplace parties in understanding their rights and duties under the Occupational Health and Safety Act (OHSA) and its regulations. This information does not constitute legal advice. To determine your rights and duties under the OHSA, please contact your legal counsel or refer to the legislation.

# Ministry of Labour, Immigration, Training and Skills Development

## Occupational Health and Safety Branch - Construction Health and Safety Program

### Section 1 – Senior Manager’s Comment

- A data error was identified and corrected. One fatality had been mistakenly counted twice due to a discrepancy between the date of occurrence and the date the worker passed away from their injuries.
  - The corrected figures are:
  - **2024 total remains at 18 fatalities**
  - **2025 year-to-date (YTD) is now 8 fatalities**
  - Both the chart and table have been updated to reflect this correction.

January 6, 2025	Burlington	Single Family Housing	Roofer (Age:20)	Worker fell from a roof on Dec. 31, 2024, succumbing to his injuries on Jan. 6, 2025	Fall – From Height
--------------------	------------	--------------------------	--------------------	---	-----------------------

- **Preventable but Persistent: 40% of Critical Injuries Demand Industry Action.** In September 2025 alone, 45 incidents were reported — 18 (40%) linked to inattention, lack of focus, or poor situational awareness.

These are basic, everyday hazards—falls on stairs, trips on flat surfaces, unsafe excavations, and unstable platforms. They are preventable yet continue to result in serious outcomes: medical treatment, lost time, and modified duties.

Most concerning is that many injuries occurred during secondary or incidental tasks—highlighting a breakdown in hazard recognition and safe work planning.

Stakeholders across the system—industry leaders, associations, inspectors, employers, and workers—share a common goal: preventing harm. But with 40% of injuries stemming from basic lapses, we must ask: *What are we missing?* How do we better embed hazard awareness, focus, and accountability into every level of work?

**Ministry of Labour, Immigration, Training and Skills Development**  
**Occupational Health and Safety Branch - Construction Health and Safety Program**

There is opportunity here: through collaboration, renewed commitment, and shared accountability, we can reverse this trend and build safer workplaces for everyone.



Sincerely, Francois Malette

A/Senior Manager  
Construction Health and Safety Program  
Occupational Health and Safety Branch  
Ontario Ministry of Labour, Training and Skills Development

# Ministry of Labour, Immigration, Training and Skills Development

## Occupational Health and Safety Branch - Construction Health and Safety Program

### Section 2 – What’s New

#### New Online Employer Portal

We’re pleased to inform you that the Ministry of Labour, Immigration, Training and Skills Development (MLITSD) is launching a new online employer portal to support the submission of various health and safety notices. This new portal, launched October 30, 2025, is part of our ongoing efforts to modernize service delivery and enhance efficiency for Ontario employers.

The portal will allow employers to:

- Create a My Ontario public secure account
- Set up a company profile and add team members to help manage notice submissions
- Choose from a variety of notice types and complete your submission online
- Save drafts and return to edit submissions as needed
- Make updates to previously submitted notices (e.g. Supervisor name and phone number, start date and end date).

The following notices will be available for online submission through the new portal:

- Notice for tunnels, shafts, caissons and cofferdams
- Notice of asbestos removal work
- Notice of asbestos work report
- Notice of diving operation
- Notice of man basket
- Notice of mining activities
- Notice of multipoint suspended scaffolds
- Notice of project
- Notice of suspended work platform
- Notice of the operation of a test drill
- Notice of trench work
- Notice of window cleaning work

Below are links to the Ministry’s website where you can choose the appropriate notice type and access the new portal. Links live as of October 30, 2025.

- [File a work notice | ontario.ca](#)
- [File a mining notice | ontario.ca](#)

For the latest **What’s New** – MLITSD articles, see: [What’s New!](#)

# Ministry of Labour, Immigration, Training and Skills Development

## Occupational Health and Safety Branch - Construction Health and Safety Program

### Section 3 – Court Bulletin(s)

## Concord Company Fined \$55,000 After Worker Injured

**Convicted:** Camp Forming Ltd., 71 Creditstone Road, Concord, Ontario, a concrete forming contractor

**Location of Workplace:** The company's facility at 71 Creditstone Road, Concord, Ontario

**Description of Offence:** A worker was injured while cleaning a conveyor while its belt was moving. The company failed, as an employer, to provide information, instruction and supervision to a worker to protect the health or safety of the worker, contrary to [section 25\(2\)\(a\)](#) of the *Occupational Health and Safety Act*.

**Date of Offence:** February 28, 2024

**Date of Conviction:** September 12, 2025

### Penalty Imposed:

- Following a guilty plea in the Provincial Offences Court in Newmarket, the company was fined \$55,000 by Justice of the Peace Rhonda Shousterman; Crown Counsel were Alicia Gordon-Fagan and Emily Jin, Student-at-Law.
- The court also imposed a 25 per cent victim fine surcharge as required by the *Provincial Offences Act*. The surcharge is credited to a special provincial government fund to assist victims of crime.

### Background:

- On February 28, 2024, a worker was cleaning one of the rollers of a Telebelt telescopic boom conveyor while its belt was in motion. The worker's upper body was inside an opening under the main conveyor system.

## **Ministry of Labour, Immigration, Training and Skills Development Occupational Health and Safety Branch - Construction Health and Safety Program**

- When the worker went to move away from the conveyor belt while it was still moving, their coverall was caught on the conveyor's belt, causing an injury.
- A Ministry of Labour, Immigration, Training and Skills Development investigation found that the worker had not been trained on the safe use, care and operation of the Telebelt conveyor system other than the general orientation training provided by the Telebelt's vendor at the time of the conveyor's delivery to the workplace.

Court Bulletins can be found here: <https://news.ontario.ca/en>

### ***Considerations from a Root Cause point of view:***

- *This is a good example of the importance for having both general training for the operation of equipment as well as site specific training for all activities, including all actual and potential hazards.*

# Ministry of Labour, Immigration, Training and Skills Development

## Occupational Health and Safety Branch - Construction Health and Safety Program

### Section 4 – Enforcement Results and Trends – September 2025

MLITSD Construction Inspectors conducted **1,622** field visits during the month of September 2025 resulting in **3,422** orders and requirements, which includes **318** Stop Work Orders accompanied by **447** Time Unknown Orders.



According to the total number of field visits, Construction Inspectors responded **449** initial events, with **156** follow up visits. The breakdown of initial events is as follows:

#### Most common orders across all Sectors - Under O.Reg. 213/91- Construction Projects

Contravention	Orders		
Fall Protection	458		<p>When evaluating risk factors associated with workplace hazards—both actual and potential—it is essential to account for contributing and compounding elements that may exacerbate an already hazardous situation.</p> <p>A review of the Orders data reveals that contraventions of individual regulatory sections may seem minor when considered in isolation. However, when these infractions are present concurrently, the cumulative risk of harm increases substantially.</p> <p>For instance, inadequate housekeeping—characterized by the accumulation of combustible materials and debris—combined with insufficient fire safety measures and the absence of an emergency response plan, creates a significantly heightened risk. This situation is further aggravated when escape routes are obstructed, severely compromising a worker’s ability to evacuate safely and promptly in the event of a fire.</p>
PPE (excluding S.26)	471		
Ladders	165		
Scaffold	157		
Emergency Management	138		
Housekeeping	133		
Stairs	125		
Equipment, General	123		
Fire Safety	97		
Access / Egress	78		
<b>SUB-TOTAL</b>	<b>1,945</b>	72.6%	
Sections 5 and 6	258	9.6%	
All other Sections	477	17.8%	
<b>TOTAL</b>	<b>2,680</b>	100%	



# Ministry of Labour, Immigration, Training and Skills Development

## Occupational Health and Safety Branch - Construction Health and Safety Program



# Ministry of Labour, Immigration, Training and Skills Development

## Occupational Health and Safety Branch - Construction Health and Safety Program



# Ministry of Labour, Immigration, Training and Skills Development

## Occupational Health and Safety Branch - Construction Health and Safety Program

### Section 5 – Critical Injuries & Fatalities: Year-to-Date Overview and Comparison

Critical Injuries	September 2025	Year to Date 2025
As defined in S.1(1) of O.Reg. 420/21 – Notices and Reports Under Sections 51 to 53 of the Act – Fatalities, Critical Injuries, Occupational Illnesses and Other Incidents	<b>45</b>	<b>285</b>
	September 2024	Year to Date 2024
	30	280

*NOTE: These figures represent preliminary data and are not to be considered official statistics from the Ministry of Labour, Immigration, Training and Skills Development. Official statistics will be issued quarterly by the Program Analysis, Evaluation and Outcomes Unit of the Occupational Health and Safety Branch of the Ministry of Labour, Immigration, Training and Skills Development. Data are subject to change due to updates in the enforcement database. Only events reported to the ministry are included here. Except for fatalities, event categories in the ministry's data set are based on what was assigned at the time of the initial report to the ministry. The reported event category may not represent what occurred at the workplace.*

### Critical Injuries – September 2025

September 2025 CRITICALS	RESS	INST	RESM	INDU	ROAD	EXCA	COMM	NECC	POWP	HYDR	SEWW	BRID	TUNN	TOTAL
Falls from Heights	4			1	1									6
Falls From Equipment	1			2			3		1					7
Falls from Ladders	4	1		2			1							8
Same level slips and trips				2	2					1	2			7
Struck by equipment				1	1						1	1	1	5
Struck by material				1		2		2						5
Electrical Contact					1									1
Other, including multiple factors, i.e. fall resulting from scaffold being struck by equipment.				1	1	1	1	1	1					6
<b>TOTAL</b>	<b>9</b>	<b>1</b>	<b>10</b>	<b>6</b>	<b>3</b>	<b>1</b>	<b>5</b>	<b>3</b>	<b>1</b>	<b>1</b>	<b>3</b>	<b>1</b>	<b>1</b>	<b>45</b>

*NOTE: To make this chart more reader friendly, columns and rows where the values are '0' have been removed.*

# Ministry of Labour, Immigration, Training and Skills Development

## Occupational Health and Safety Branch - Construction Health and Safety Program

### Critical Injuries - Year to Date 2025

YTD 2025 CRITICALS	RESS	INST	RESM	INDU	ROAD	EXCA	COMM	NECC	RAIL	POWP	ETTL	HYDR	SEWW	BRID	TUNN	WIND	MARE	PAVE	GAS	CAIS	TOTAL	
Falls from Heights	14	2	7	4			1	2	1													31
Falls From Equipment	4	8	12	2	1		4				1	1	1	2				1				37
Falls from Ladders	6	7	12	2			9						1				1			1		39
Same level slips and trips	14	4	20	10	3		6	4	1	1	1	1	3	1	1		1			2	1	73
Struck by equipment	1	6	2	1	1		2	2	2	1			2	1	1							19
Struck by material	4	1	13	2	2		4	4					1	2	1							34
Electrical Contact				1			1					1					1					4
Excavation Collapse			1																			1
Other, including multiple factors, i.e. fall resulting from scaffold being struck by equipment.																						
	5	3	14	4	2	3	5	1	1	1		2	4					2				47
<b>TOTAL</b>	<b>47</b>	<b>26</b>	<b>85</b>	<b>27</b>	<b>9</b>	<b>4</b>	<b>33</b>	<b>12</b>	<b>2</b>	<b>4</b>	<b>3</b>	<b>6</b>	<b>13</b>	<b>3</b>	<b>1</b>	<b>2</b>	<b>1</b>	<b>3</b>	<b>3</b>	<b>1</b>	<b>285</b>	

NOTE: To make this chart more reader friendly, columns and rows where the values are '0' have been removed.

	Date of Incident	Municipality (Where incident occurred)	Sector (Refer to Sector Description Table)	Occupation (Of Injured Person)	Details (As reported at the time of incident)	Category (Initial Cause as reported)
1	September 2, 2025	Brantford	Industrial Building Construction	Labourer	Worker was electrocuted while clearing scrap, resulting in 3 <sup>rd</sup> degree burns and life-threatening injuries.	Electrical Contact
2	September 3, 2025	London	Industrial Building Construction	Roofer	Worker suffered a broken wrist and multiple other fractures after falling from height.	Fall – From Height
3	September 3, 2025	Toronto	Single Family Housing	Worker	Worker suffered fractured wrist after falling into an open excavation.	Fall – From Height
4	September 3, 2025	Brockville	Highway & Road Construction	Worker	Worker suffered critical injury to left arm after being	Stuck By - Material

**Ministry of Labour, Immigration, Training and Skills Development**  
**Occupational Health and Safety Branch - Construction Health and Safety Program**

	<b>Date of Incident</b>	<b>Municipality</b> (Where incident occurred)	<b>Sector</b> (Refer to Sector Description Table)	<b>Occupation</b> (Of Injured Person)	<b>Details</b> (As reported at the time of incident)	<b>Category</b> (Initial Cause as reported)
					struck by material that came loose.	
5	September 4, 2025	Kitchener	Apartment & Other Multiple Housing	Landscaper	Worker suffered broken ankle after coming into contact with a machine on site.	Struck By - Equipment
6	September 6, 2025	Toronto	Apartment & Other Multiple Housing	Labourer	Worker lost consciousness after falling from a trailer while unloading it.	Fall – From Equipment
7	September 6, 2025	West Grey	Single Family Housing	Labourer	Worker sustained a critical injury to left leg after falling from a ladder.	Fall – From Ladder
8	September 8, 2025	Orillia	Industrial Building Construction	Pipefitter	Worker sustained multiple burns after an explosion.	NEC - Construction
9	September 8, 2025	Toronto	High-Rise (10 storeys or more)	Foreman	Worker sustained life-threatening injuries after falling approx. 12ft.	Fall – From Height
10	September 8, 2025	Toronto	Residential Building Construction	Worker	Worker sustained life-threatening injuries after falling approx. 15ft form a ladder.	Fall – From Ladder

**Ministry of Labour, Immigration, Training and Skills Development**  
**Occupational Health and Safety Branch - Construction Health and Safety Program**

	<b>Date of Incident</b>	<b>Municipality</b> (Where incident occurred)	<b>Sector</b> (Refer to Sector Description Table)	<b>Occupation</b> (Of Injured Person)	<b>Details</b> (As reported at the time of incident)	<b>Category</b> (Initial Cause as reported)
11	September 8, 2025	Hunstville	Residential Building Construction	Concrete Truck Operator	Worker fractured his ankle after slipping and falling.	Fall – Same Level
12	September 8, 2025	Toronto	Apartment & Other Multiple Housing	Drywaller	Worker suffered fractured arm after falling from a platform.	Fall – From Equipment
13	September 8, 2025	North York	Sewer/Watermain Construction	Traffic Supervisor	Worker tripped on debris, resulting in a fractured arm.	Fall – Same Level
14	September 8, 2025	Oakville	Single Family Housing	Carpenter	Worker suffered critical injury after falling through a floor opening.	Fall – From Height
15	September 9, 2025	Trenton	Sewer / Watermain Construction	Worker	Worker turned and tripped over pile of dirt, causing him to fall, resulting in a fractured wrist.	Fall – Same Level
16	September 9, 2025	Oakville	Industrial Building Construction	Worker	Worker suffered fracture to the right fibula after slipping while descending stairs.	Fall – Same Level
17	September 10, 2025	Milton	Sewer / Watermain Construction	Worker	Worker was struck in the eye by equipment, resulting in a loss of vision in the one eye.	Struck By - Equipment

**Ministry of Labour, Immigration, Training and Skills Development**  
**Occupational Health and Safety Branch - Construction Health and Safety Program**

	<b>Date of Incident</b>	<b>Municipality</b> (Where incident occurred)	<b>Sector</b> (Refer to Sector Description Table)	<b>Occupation</b> (Of Injured Person)	<b>Details</b> (As reported at the time of incident)	<b>Category</b> (Initial Cause as reported)
18	September 11, 2025	Toronto	Bridge Construction	Worker	Worker suffered a critical injury to left hand after losing control of the drill while trying to balance and drill at the same time.	Struck By - Equipment
19	September 11, 2025	Barrie	Institutional Building Construction	Labourer	Worker fractured his ankle after falling approx. 8ft from a ladder.	Fall – From Ladder
20	September 12, 2025	Ottawa	Commercial Building Construction	Labourer	Worker suffered a broken leg after falling approx. 10ft from a platform.	Fall – From Equipment
21	September 12, 2025	Scarborough	Commercial Building Construction	Drywaller	Worker suffered fractured leg after a fall.	Fall – From Equipment
22	September 12, 2025	Chatham - Kent	NEC - Construction	Driver	Worker was struck by a vehicle while waiting as a mechanic worked on his truck on the side of the road.	Struck By - Vehicle
23	September 15, 2025	London	Moving of a Building / Structure	Labourer	Worker was struck by falling material while dismantling an amusement ride, resulting in a loss of consciousness.	Struck By - Material

**Ministry of Labour, Immigration, Training and Skills Development**  
**Occupational Health and Safety Branch - Construction Health and Safety Program**

	<b>Date of Incident</b>	<b>Municipality</b> (Where incident occurred)	<b>Sector</b> (Refer to Sector Description Table)	<b>Occupation</b> (Of Injured Person)	<b>Details</b> (As reported at the time of incident)	<b>Category</b> (Initial Cause as reported)
24	September 15, 2025	Hamilton	Tunnel	Worker	Worker lost consciousness and suffered a broken leg after being struck by equipment.	Struck By - Equipment
25	September 16, 2025	Leamington	Single Family Housing	Roofer	Worker lost consciousness after falling from a ladder.	Fall – From Ladder
26	September 16, 2025	Toronto	Commercial Building Construction	Film Production	Worker fell from a ladder, resulting in a broken ankle.	Fall – From Ladder
27	September 17, 2025	Ottawa	Apartment & Other Multiple Housing	Labourer	Worker sustained a fractured ankle after rolling it while stepping out of an elevated work platform.	Fall – Same Level
28	September 18, 2025	York	Single Family Housing	Worker	Worker sustained fractured hips, ribs and head injuries after a fall.	Fall – From Height
29	September 18, 2025	Tiverton	Hydroelectric Power Plants & Rel	Boilermaker	Worker suffered a broken shoulder after falling from a work platform.	Fall – From Equipment
30	September 19, 2025	Newmarket	Single Family Housing	Roofer	Worker suffered life threatening head injury after	Fall – From Ladder

**Ministry of Labour, Immigration, Training and Skills Development**  
**Occupational Health and Safety Branch - Construction Health and Safety Program**

	<b>Date of Incident</b>	<b>Municipality</b> (Where incident occurred)	<b>Sector</b> (Refer to Sector Description Table)	<b>Occupation</b> (Of Injured Person)	<b>Details</b> (As reported at the time of incident)	<b>Category</b> (Initial Cause as reported)
					falling approx. 6ft from a ladder.	
31	September 19, 2025	Toronto	Subway	Form Worker	Worker suffered broken bones in left foot after being struck by falling pipe.	Struck By - Material
32	September 19, 2025	Waterloo	Medium-Rise (4 to 9 storeys)	Painter	Worker suffered a broken arm after tripping over the spray house landing.	Fall – Same Level
33	September 23, 2025	Schomberg	Highway & Road Construction (including ice roads)	Labourer	Worker suffered a broken arm while unloading material from a truck.	Struck By – Material
34	September 23, 2025	Mississauga	Medium-Rise (4 to 9 storeys)	Form Worker	Worker suffered a broken arm after having it caught between joist and scaffolding.	NEC-Construction
35	September 24, 2025	Copper Cliff	Commercial Building Construction	Worker	Worker sustained a critical injury after being struck by a vehicle.	Struck By - Vehicle
36	September 24, 2025	Tiverton	Industrial Building Construction	Worker	Worker suffered a broken hand after falling while descending stairs.	Fall – Same Level

**Ministry of Labour, Immigration, Training and Skills Development**  
**Occupational Health and Safety Branch - Construction Health and Safety Program**

	<b>Date of Incident</b>	<b>Municipality</b> (Where incident occurred)	<b>Sector</b> (Refer to Sector Description Table)	<b>Occupation</b> (Of Injured Person)	<b>Details</b> (As reported at the time of incident)	<b>Category</b> (Initial Cause as reported)
37	September 24, 2025	Toronto	Hydro	Delivery Driver	Worker suffered broken ankle after tripping while walking on site.	Fall – Same Level
38	September 25, 2025	Hamilton	Single Family Housing	Roofer	Worker suffered fractured ankle after falling from height.	Fall – From Height
39	September 26, 2025	Toronto	Commercial Building Construction	Painter	Worker suffered broken arm after falling from scaffold.	Fall – From Equipment
40	September 26, 2025	Port Perry	Highway & Road Construction	Signaller	Worker suffered broken leg after being struck by a vehicle.	Struck By – Vehicle
41	September 29, 2025	Toronto	High-Rise (10 storeys or more)	Glazer	Worker suffered broken leg as a result of falling while carrying a window to install.	Struck By - Material
42	September 29, 2025	Ryerson	Single Family Housing	Carpenter	Worker sustained broken leg and impalement injuries after falling from scaffold onto rebar.	Fall – From Equipment
43	September 29, 2025	St. Thomas	Industrial Building Construction	Concrete Worker	Worker suffered critical injury after being struck in the head by the chute	Struck By - Equipment

**Ministry of Labour, Immigration, Training and Skills Development**  
**Occupational Health and Safety Branch - Construction Health and Safety Program**

	<b>Date of Incident</b>	<b>Municipality</b> (Where incident occurred)	<b>Sector</b> (Refer to Sector Description Table)	<b>Occupation</b> (Of Injured Person)	<b>Details</b> (As reported at the time of incident)	<b>Category</b> (Initial Cause as reported)
					of the concrete truck.	
44	September 29, 2025	Copper Cliff	Excavation	Dump Truck Operator	Worker sustained critical injuries after falling asleep while driving, hitting a barrier.	NEC - Construction
45	September 30, 2025	Quinte West	Single Family Housing	HVAC Technician	Worker sustained life threatening injuries after falling multiple levels.	Fall – From Ladder

# Ministry of Labour, Immigration, Training and Skills Development

## Occupational Health and Safety Branch - Construction Health and Safety Program

### Fatality Summary – September 2025

Fatal Injuries	September 2025	Year to Date 2025
	1	8
	September 2024	Year to Date 2024
	0	13

### Fatalities – September 2025

September 2025 FATALS		Total
Struck by equipment	1	1
<b>TOTAL</b>	<b>1</b>	<b>1</b>

*NOTE: To make this chart more reader friendly, columns and rows where the values are '0' have been removed.*

### Fatalities – Year to Date 2025

YTD 2025 FATALS	RESS	RESM	NECC	HYDR	PAVE	Total
Falls from Heights	1	1				2
Struck by equipment	1		1	1		3
Struck by material	1					1
Electrical Contact		1				1
Other, including multiple factors, i.e. fall resulting from scaffold being struck by equipment.					1	1
<b>TOTAL</b>	<b>3</b>	<b>2</b>	<b>1</b>	<b>1</b>	<b>1</b>	<b>8</b>

*NOTE: To make this chart more reader friendly, columns and rows where the values are '0' have been removed.*

**Ministry of Labour, Immigration, Training and Skills Development**  
**Occupational Health and Safety Branch - Construction Health and Safety Program**

	<b>Date of Incident</b>	<b>Municipality</b> (Where incident occurred)	<b>Sector</b> (Refer to Sector Description Table)	<b>Occupation</b> (Of Injured Person)	<b>Details</b> (As reported at the time of incident)	<b>Category</b> (Initial Cause as reported)
8	September 18, 2025	Hanmer	Single Family Housing	Excavator	Worker was crushed when trying to exit the excavator after it began to sink and rolled over onto the worker.	Stuck by - Vehicle
7	August 22, 2025	Merrickville-Wolford	Asphalt Paving	Signaller (Age:61)	Worker was struck by a reversing vehicle, succumbing to her injuries later the same day	Struck by - Vehicle
6	July 3, 2025	Toronto	Single Family Housing	Rofer	Worker sustained fatal injuries after falling from height.	Fall – From Height
5	April 20, 2025	Ottawa	Single Family Housing	Foundation Cribbing and Installation	Workers sustained fatal injuries after being crushed by material	Struck by - Material
4	March 19, 2025	Niagara Falls	Apartment and Other Multiple Housing	Rofer	Worker sustained fatal injuries when his aluminum ladder	Electrocution

**Ministry of Labour, Immigration, Training and Skills Development**  
**Occupational Health and Safety Branch - Construction Health and Safety Program**

	<b>Date of Incident</b>	<b>Municipality</b> (Where incident occurred)	<b>Sector</b> (Refer to Sector Description Table)	<b>Occupation</b> (Of Injured Person)	<b>Details</b> (As reported at the time of incident)	<b>Category</b> (Initial Cause as reported)
					contacted an energized line while lowering the ladder	
3	February 27, 2025	Kynoch	Hydro	Technician (59 Yrs. Old)	Worker sustained a fatal injury after being struck by bulldozer	Struck by - Equipment
2	February 3, 2025	Ottawa	Apartment and Other Multiple Housing	Labourer (32 Yrs. Old)	Worker fell through a floor opening, approx. 30ft, succumbing to his injuries	Fall – From Height
1	January 24, 2025	Goderich	NEC – Construction (Wind Turbine)	Crane Apprentice	Worker sustained fatal injuries after being struck by a skid steer	Struck by - Equipment
	January 6, 2025	Burlington	Single Family Housing	Rofer (Age:20)	Worker fell from a roof on Dec. 31, 2024, succumbing to his injuries on Jan. 6, 2025	Fall – From Height

**Ministry of Labour, Immigration, Training and Skills Development**  
**Occupational Health and Safety Branch - Construction Health and Safety Program**

SECTOR DESCRIPTION	SHORT DESC
Asbestos Removal - Type 1	ASB1
Asbestos Removal - Type 2	ASB2
Asbestos Removal - Type 3	ASB3
Bridge Construction	BRID
Cable	CABL
Caisson	CAIS
Cofferdam	COFF
Commercial Building Construction	COMM
Diving Construction	DCON
Diving Environmental	DENV
Diving Industrial	DIND
Diving Mining	DMIN
Electrical Towers & Transmission Lines	ETTL
Excavation	EXCA
Gas Service Connection	GAS
Excavation - Grading	GRAD
Hydro	HYDR
Industrial Building Construction	INDU
Institutional Building Construction	INST
Marine Construction	MARE
Mining Plant Construction	MINP
Moving of a Building/Structure	MOVE
NEC – Construction (NEC: not elsewhere captured)	NECC
NEC – Diving (NEC: not elsewhere captured)	NECD
Asphalt Paving	PAVE
Pipeline	PIPE
Hydroelectric Power Plants & Rel	POWP
Railway	RAIL
Apartment & Other Multiple Housing	RESM
Single Family Housing	RESS
Highway & Road Construction	ROAD
Sewer/Watermain Construction	SEWW
Shaft Construction	SHAF
Shipbuilding & Repair	SHIP

**Ministry of Labour, Immigration, Training and Skills Development**  
**Occupational Health and Safety Branch - Construction Health and Safety Program**

Subway	SUBW
Telephone	TELE
Trenching	TREN
Tunnel	TUNN
Well Drilling	WELL
Window Cleaning Services	WIND