Ministry of Labour, Immigration, Training and Skills Development

Occupational Health and Safety Branch - Construction Health and Safety Program

Report for the Labour-Management Network
November 2026

Monthly Statistics

Reporting Month	Fatalities	Critical Injuries	Total
September 2026	**1**	**51**	**52**

Fatality & Critical Injury Overview

Reporting Months	Fatalities	Critical Injuries	Total
Year to Date 2026	**10**	**358**	**369**

Resources to help you achieve compliance on construction projects and window cleaning operations

General requirements
Access to and egress from a work area
Asbestos on construction projects
Diving operations
Electrical hazards
Equipment
Excavations
Fall protection and roofing
Forms, formwork, falsework, and re-shoring
Housekeeping, fire protection, public way protection, traffic control, and hot tar or bitumen tankers or kettles
Hygiene
Window cleaning operations
Workplace Hazard Alerts I Ontario.ca

Disclaimer: This information has been prepared to assist workplace parties in understanding their rights and duties under the Occupational Health and Safety Act (OHSA) and its regulations. This information does not constitute legal advice. To determine your rights and duties under the OHSA, please contact your legal counsel or refer to the legislation.

Section 1 – Senior Manager's Comment

As we slide into November (where did the fall go??), I wanted to highlight some of the seasonal hazards that everyone should be considering. We've got warm days and cold nights which can lead to slippery conditions in the morning. The angle of the sun in late afternoons is making visibility more challenging for both operators and workers. The clocks will be turning back which can throw off some people for a short while as they get used to the time change. It's going to be important to keep everyone focused on their tasks. Again, as I look at the critical injuries in the report, there seems to be aspects of distraction, being hurried, or not being fully engaged in the environment. It's a good time to step up supervisor walk throughs, H&S rep/JHSC member inspections, WTC meetings, to make sure we're all focused on safety.

I saw an interesting article on CBC back on Oct 12th, which reported that the OPP has laid charges against 2 owners and a business for criminal negligence causing death for a workplace fatality. I don't have any other details but it's a reminder that there are police forces still doing C-45 work.

It was great for my team and I to meet with many of the PLMHSC sub-committee co-chairs on October 7th. The discussions were great and I enjoyed listing to the ideas coming from your groups.

Sincerely, Chris Boccinfuso

A/Senior Manager
Construction Health and Safety Program
Occupational Health and Safety Branch
Ontario Ministry of Labour, Training and Skills Development

Section 2 – What's New

Ontario helping more students explore rewarding careers in the skilled trades

The Ontario government is kicking off its fifth annual Level Up! skilled trades career fairs to introduce students, families and jobseekers across Ontario to in-demand careers in the skilled trades. Through multi-day events planned in 12 communities, the 2026 fairs are expected to reach more than 60,000 people and will include open house sessions and interactive exhibitions that will inspire the next generation of workers to build the homes, highways, hospitals, schools and critical infrastructure that the province needs.

Learn more

For the latest **What's New** – MLITSD articles, see: What's New!

Section 3 – Court Bulletin(s)

Workplace Injury Results in $65,000 Fine for London Company

Convicted: J-AAR Structures Limited, 3003 Page Street, London, Ontario, a large concrete supply and concrete formwork erector operating in southern Ontario

Location of Workplace: A construction project located at 110 Waterloo Street, London Ontario

Description of Offence: A worker was injured by exposed rebar after falling from a ladder. The employer failed to ensure the measures and procedures prescribed by section 36 of Ontario Regulation 213/91 (Construction Projects) were carried out, contrary to section 25(1)(c) of the *Occupational Health and Safety Act.*

Date of Offence: September 6, 2024
Date of Conviction: September 3, 2026
Penalty Imposed:

- Following a guilty plea in the Provincial Offences Court in London, J-AAR Structures Limited was fined $65,000 by Justice of the Peace Kristine M. Diaz; Crown Counsel was Dan Phelan.
- The court also imposed a 25 per cent victim fine surcharge as required by the *Provincial Offences Act*. The surcharge is credited to a special provincial government fund to assist victims of crime.

Background:

- On September 6, 2024, a worker was using a ladder to access the interior work platform of concrete formwork for a new stairwell in a parking garage. The ladder was placed against a concrete wall form.
- As the worker approached the top of the ladder, it slipped. The worker fell approximately eight feet towards vertical rebar that was protruding from the foundation. Upon landing, the worker sustained an injury.

- A Ministry of Labour, Immigration, Training and Skills Development investigation found that the protruding rebar had not been covered or protected to mitigate against the protrusion hazard.

Construction Companies Fined $85,000 Total After Workers Exposed to Carbon Monoxide

Convicted: Fieldgate Construction Management Inc., a construction and development company located at 5400 Yonge Street, Suite 501, North York, Ontario, and Metro Concrete Works [2016] Inc., a concrete placing and finishing company located at 90 Gregory Scott Drive, Vaughan, Ontario

Location of Workplace: 5868 Yonge Street, Toronto, Ontario

Description of Offence: Workers experienced health effects following exposure to carbon monoxide in the workplace. Fieldgate Construction Management Inc. failed, as the constructor, to ensure that the measures and procedures prescribed by section 47(3) of Ontario Regulation 213/91 were carried out, contrary to section 23(1)(b) of the *Occupational Health and Safety Act,* and Metro Concrete Works [2016] Inc. failed, as an employer, to ensure compliance with the same regulatory requirement contrary to section 25(1)(c) of the *Occupational Health and Safety Act.*

Date of Offence: July 4, 2023
Date of Conviction: August 28, 2026
Penalty Imposed:

- Following a guilty plea in the Provincial Offences Court in Toronto, Fieldgate Construction Management Inc. was fined $55,000 and Metro Concrete Works [2016] Inc. was fined $30,000 by Justice of the Peace Esther N. Daniel; Crown Counsel were Alicia Gordon-Fagan and Kennedy McKee-Braide, Student-at-Law.
- The court also imposed a 25 per cent victim fine surcharge as required by the *Provincial Offences Act*. The surcharge is credited to a special provincial government fund to assist victims of crime.

Ministry of Labour, Immigration, Training and Skills Development

Occupational Health and Safety Branch - Construction Health and Safety Program

Background:

- Fieldgate Construction Management Inc. (FCML) was the constructor for a project to build a new car dealership. The project included a three-level parking garage.
- Metro Concrete Works [2016] Inc. (Metro) was subcontracted by FCML to install an approximately three-inch concrete topping layer over the structural concrete floor at the project.
- On the day of the incident, workers were finishing concrete using hand tools and gasoline-powered concrete finishing machines.
- A Metro worker and several other workers began to feel unwell. Emergency Medical Services attended the project and treated multiple workers for carbon monoxide exposure.
- Toronto Fire Services tested the air and found elevated levels of carbon monoxide in the parking garage and began ventilating the building.
- FCML and Metro were testing and monitoring air quality in the parking garage. However, initial testing showed that workers were exposed to carbon monoxide levels that exceeded the applicable limits.
- A Ministry of Labour, Immigration, Training and Skills Development investigation found that Level P2, where workers were using the gasoline-powered concrete finishing equipment, was not being adequately tested for airborne concentrations of carbon monoxide in accordance with section 47(3) of Ontario Regulation 213/91.

Court Bulletins can be found here: https://news.ontario.ca/en

Section 4 – Enforcement Results and Trends – September 2026

MLITSD Construction Inspectors conducted **1,736** field visits to **1,319** workplaces in August 2026 resulting in **3,987** total enforcement actions. Below is a list of the most common Orders issued.



Ministry of Labour, Immigration, Training and Skills Development

Occupational Health and Safety Branch - Construction Health and Safety Program



Classification	Count	Percentage
Complaints	392	77.0%
Injuries and Incidents	82	16.1%
Occurrences	33	6.5%
Reprisals	1	0.2%
Occupational Illness	1	0.2%

Occurences - September 2026	Electical Contact	Powerline Contact	Releast to Atmosphere	Fire	Equipment Failure/Damage	NEC - Construction	Discovery of Asbestos	Total
ICI	7	1	1	1	2	1	1	14
Infrastructure	1							1
NEC - Construction		2						2
Power	2				1			3
Residential	1		1		2			4
Underground	1	3	1	1		1		7
	12	6	3	2	5	2	1	31

OHSA S.53 - Occurrence means:

Accident, premature or unexpected explosion, fire, flood or inrush of water, failure of any equipment, machine, device, article or thing, cave-in, subsidence, rockburst, or other prescribed incident occurs at a project.

Ministry of Labour, Immigration, Training and Skills Development

Occupational Health and Safety Branch - Construction Health and Safety Program

Section 5 – Critical Injuries & Fatalities:

Year-to-Date Overview and Comparison

Fatal Injuries	September 2026	Year to Date 2026
	1	**10**
	September 2025	Year to Date 2025
	0	8

Fatalities – Year to Date 2026

Year to Date 2026 FATALS	RESS	RESM	INDU	COMM	NECC	SEWW		Total
Falls from Heights	1		1	1				3
Falls From Equipment		1						1
Falls from Ladders		1						1
Struck by equipment			1					1
Struck by vehicle						1		1
Other, including multiple factors, i.e. fall resulting from scaffold being struck by equipment.				1	2			3
TOTAL	**1**	**2**	**2**	**2**	**2**	**1**		**10**

Fatality Summary - 2026

	Date of Incident	Municipality (Where incident occurred)	Sector (Refer to Sector Description Table)	Occupation (Of Injured Person)	Details (As reported at the time of incident)	Category (Initial Cause as reported)
10	**September 16, 2026**	**Brampton**	**Sewer / Watermain**	**Watermain Worker**	**Worker suffered fatal injury after being struck by a vehicle.**	**Struck By - Vehicle**

Ministry of Labour, Immigration, Training and Skills Development

Occupational Health and Safety Branch - Construction Health and Safety Program

	Date of Incident	**Municipality** (Where incident occurred)	**Sector** (Refer to Sector Description Table)	**Occupation** (Of Injured Person)	**Details** (As reported at the time of incident)	**Category** (Initial Cause as reported)
9	June 22, 2026	Brampton	Commercial Building Construction	Concrete Finisher	Worker suffered fatal injuries after falling approx. 10ft, landing on the chop saw.	NEC - Construction
8	June 17, 2026	Courtice	Commercial Building Construction	Welder	Worker suffered fatal injuries after falling from height.	Fall – From Height
7	June 2, 2026	Marmora	Residential Building Construction	Roofer	Worker sustained fatal injuries after falling from scaffold.	Fall – From Equipment
6	May 27, 2026	Brampton	Industrial Building Construction	Worker	Worker sustained fatal injuries after being crushed by equipment.	Struck By - Equipment
5	May 19, 2026	Toronto	Single Family Housing	Roofer	Worker fell approx. 15ft, resulting in fatal injuries.	Fall – From Height
4	April 24, 2026	Brantford	Industrial Building Construction	Roofer	Worker fell approx. 30ft through an opening, resulting in fatal injuries.	Fall – From Height

Ministry of Labour, Immigration, Training and Skills Development

Occupational Health and Safety Branch - Construction Health and Safety Program

	Date of Incident	**Municipality** (Where incident occurred)	**Sector** (Refer to Sector Description Table)	**Occupation** (Of Injured Person)	**Details** (As reported at the time of incident)	**Category** (Initial Cause as reported)
3	March 18, 2026	Erieau	Diving	Diver	Worker asphyxiated during a dive.	NEC - Construction
2	February 20, 2026	Spencerville	Residential Building Construction	Siding Installer	Worker fell from a ladder on Feb. 20, 2026, and succumbed to their injuries on Feb 24, 2026	Fall – From Ladder
1	January 26, 2026	Hamilton	Ship Building and Repair	Skid Steer Operator	Worker drowned after the skid steer he was operating to clear snow was submerged in water.	NEC - Construction

Ministry of Labour, Immigration, Training and Skills Development

Occupational Health and Safety Branch - Construction Health and Safety Program

Critical Injuries	September 2026	Year to Date 2026
As defined in S.1(1) of O.Reg. 420/21 – Notices and Reports Under Sections 51 to 53 of the Act – Fatalities, Critical Injuries, Occupational Illnesses and Other Incidents	**51**	**359**
	September 2025	Year to Date 2025
	45	285

NOTE: These figures represent preliminary data and are not to be considered official statistics from the Ministry of Labour, Immigration, Training and Skills Development. Official statistics will be issued quarterly by the Program Analysis, Evaluation and Outcomes Unit of the Occupational Health and Safety Branch of the Ministry of Labour, Immigration, Training and Skills Development. Data are subject to change due to updates in the enforcement database. Only events reported to the ministry are included here. Except for fatalities, event categories in the ministry's data set are based on what was assigned at the time of the initial report to the ministry. The reported event category may not represent what occurred at the workplace.

Section 1 of O.Reg. 420/21 states:
"critically injured" *means an injury of a serious nature that*

Sub-Clause	September 2026		YTD 2026	
(a) places life in jeopardy	**10**		**63**	
(b) produces unconsciousness	**11**		**56**	
(c) results in substantial loss of blood	**0**		**5**	
(d) involves the fracture of a leg or arm but not a finger or toe	**28**		**232**	
	Arms/Hands	Legs/Feet	Arms/Hands	Legs/Feet
	10	18	79	153
(e) involves the amputation of a leg, arm, hand or foot but not a finger or toe	**2**		**3**	
(f) consists of burns to a major portion of the body	**0**		**0**	
(g) causes the loss of sight in an eye	**0**		**0**	
Total	**51**		**359**	

Ministry of Labour, Immigration, Training and Skills Development

Occupational Health and Safety Branch - Construction Health and Safety Program

Critical Injuries – September 2026

September 2026 CRITICALS	RESS	INST	RESM	INDU	ROAD	EXCA	COMM	SEWW	BRID	TELE	PAVE	PIPE		TOTAL
Falls from Heights	6		2				1							**9**
Falls From Equipment	2	1					1							**4**
Falls from Ladders	1	2	2	1						1				**7**
Same level slips and trips		1		4		1	1							**7**
Struck by equipment		1									1			**2**
Struck by material	1		2	1				1	1					**6**
Other, including multiple factors, i.e. fall resulting from scaffold being struck by equipment.	2	2	1	3	1	1	2				3	1		**16**
						0								
TOTAL	12	7	7	9	1	2	5	1	1	1	4	1		**51**

Critical Injuries – Year to Date 2026

Split 1

Year to Date 2026 CRITICALS	RESS	INST	RESM	INDU	ROAD	EXCA	COMM	NECC	RAIL	POWP	ETTL
Falls from Heights	16	2	13	1		1	8	1			
Falls From Equipment	7	6	6	2		1	8			1	
Falls from Ladders	10	8	19	3	1		6	1		1	
Same level slips and trips	7	13	20	15	3	3	8	4		1	2
Struck by equipment		3	5	1	2	2	2	1	1		
Struck by material	5	6	9	7	4		4		3	1	1
Struck by vehicle					3		1	1			
Electrical Contact							1				
Other, including multiple factors, i.e. fall resulting from scaffold being struck by equipment.	12	5	13	9	4	4	9	7		1	1
TOTAL	**57**	**43**	**85**	**38**	**17**	**11**	**47**	**15**	**4**	**5**	**4**

Split 2

Ministry of Labour, Immigration, Training and Skills Development

Occupational Health and Safety Branch - Construction Health and Safety Program

Year to Date 2026 CRITICALS	HYDR	SEWW	BRID	TELE	MARE	PAVE	GAS	MINP	PIPE	CAIS		TOTAL
Falls from Heights	1											**43**
Falls From Equipment												**31**
Falls from Ladders				1								**50**
Same level slips and trips		3	2			1	1	1				**84**
Struck by equipment		1		1		2						**21**
Struck by material	2	1	1					1				**45**
Struck by vehicle						1						**6**
Electrical Contact												**1**
Other, including multiple factors, i.e. fall resulting from scaffold being struck by equipment.		1		1	2	6		1	1	1		**78**
TOTAL	**3**	**6**	**3**	**3**	**2**	**10**	**1**	**3**	**1**	**1**		**359**

	Date of Incident	**Municipality** (Where incident occurred)	**Sector** (Refer to Sector Description Table)	**Occupation** (Of Injured Person)	**Details** (As reported at the time of incident)
NEC – Construction (16)					
1	September 2, 2026	The Cache	Single Family Housing	Roofer	Worker lost consciousness after striking his knee with his hammer.
2	September 2, 2026	Lambton Shores	Industrial Building Construction	Operator	Worker suffered fractured leg after he struck a pole while his leg was outside the cab of the utility cart he was operating.
3	September 3, 2026	Toronto	Institutional Building Construction	Flooring Installer	Worker fractured multiple fingers after his hand was pull into an operating drill.
4	September 9, 2026	North Bay	Industrial Building Construction	Labourer	Worker suffered a fractured leg after falling while unpacking a television.

Ministry of Labour, Immigration, Training and Skills Development

Occupational Health and Safety Branch - Construction Health and Safety Program

	Date of Incident	**Municipality** (Where incident occurred)	**Sector** (Refer to Sector Description Table)	**Occupation** (Of Injured Person)	**Details** (As reported at the time of incident)
5	September 14, 2026	Woodbridge	Excavation - Grading	Driver	Worker suffered life threatening head injuries after his truck flipped on its side.
6	September 14, 2026	Port Hope	Excavation	Iron Worker	Worker fractured multiple fingers after they were pinched between two steel sheets being installed.
7	September 15, 2026	Ottawa	Commercial Business Construction	Electrician	Worker lost consciousness after being struck by a rope under tension became loose, causing the worker to fall and hit his head on the curb.
8	September 15, 2026	Oakville	Industrial Building Construction	Worker	Worker lost consciousness after being stung by a bee, causing him to fall and endure head injury after striking the ground.
9	September 16, 2026	Newmarket	Pipeline	Arborist	Worker suffered fracture to both legs as the tree he was cutting down landed on him.
10	September 18, 2026	Hamilton	Commercial Building Construction	Worker	Work lost consciousness.
11	September 21, 2026	Toronto	Institutional Building Construction	Electrician	Worker lost consciousness after suffering a laceration and seeing his own blood.
12	September 21, 2026	Concord	Single Family Housing	Roofer	Worker lost consciousness after the structure he was working on collapsed.

	Date of Incident	**Municipality** (Where incident occurred)	**Sector** (Refer to Sector Description Table)	**Occupation** (Of Injured Person)	**Details** (As reported at the time of incident)
13	September 22, 2026	Brantford	Asphalt Paving	Worker #1	Worker found unconscious in a confined space.
14	September 22, 2026	Brantford	Asphalt Paving	Worker #2	Worker found unconscious in a confined space.
15	September 28, 2026	Beckwith	Asphalt Paving	Signaller	Worker lost consciousness, causing him to fall and strike his head.
16	September 30, 2026	London	Apartment & Other Multiple Housing	Operator	Worker fractured his ankle after jumping from the crane.
Fall – From Height (9)					
1	September 1, 2026	Ottawa	Single Family Housing	Drywaller	Worker suffered fractured arm/wrist after falling through a floor opening.
2	September 2, 2026	Ottawa	Apartment & Other Multiple Housing	Labourer	Worker fell approx. 4m through a floor opening resulting in a fractured ankle.
3	September 8, 2026	Toronto	Single Family Housing	Painter	Worker suffered life threatening injuries after falling from the roof.
4	September 8, 2026	Owen Sound	Single Family Housing	Roofer	Worker suffered critical injuries after falling approx. 18ft from the roof.
5	September 10, 2026	St Thomas	Commercial Building Construction	Flat Roofer	Worker suffered life threatening head injuries after falling approx. 20ft from roof.

	Date of Incident	**Municipality** (Where incident occurred)	**Sector** (Refer to Sector Description Table)	**Occupation** (Of Injured Person)	**Details** (As reported at the time of incident)
6	September 22, 2026	Ottawa	Single Family Housing	Roofer	Worker suffered life threatening injuries after falling from the roof.
7	September 23, 2026	Georgian Bay	Single Family Housing	Framer	Worker suffered fractured leg after falling approx. 12ft from a joist.
8	September 30, 2026	Bobcaygeon	Apartment & Other Multiple Housing	Roofer	Worker suffered critical injury after falling 3 storeys.
9	September 30, 2026	Etobicoke	Single Family Housing	Roofer	Worker suffered critical injuries after falling from the roof.
Fall – From Ladder (7)					
1	September 1, 2026	Ottawa	Telephone	Fibre Optics Technician	Worker suffered spinal and leg injuries after falling from a ladder.
2	September 10, 2026	Sarnia	Institutional Building Construction	Painter	Worker was found unconscious after falling from a ladder.
3	September 14, 2026	Oshawa	Institutional Building Construction	Worker	Worker fractured his leg after a misstep on a ladder, causing him to fall.
4	September 16, 2026	Hamilton	Apartment & Other Multiple Housing	Carpenter	Worker suffered fractured wrist after a misstep from a ladder, causing him to fall.
5	September 18, 2026	Kitchener	Apartment & Other Multiple Housing	Electrician	Worker suffered fractured arm and wrist after a fall from a ladder.

	Date of Incident	**Municipality** (Where incident occurred)	**Sector** (Refer to Sector Description Table)	**Occupation** (Of Injured Person)	**Details** (As reported at the time of incident)
6	September 22, 2026	Perth	Single Family Housing	Carpenter	Worker suffered fractured arm and leg after falling from a ladder.
7	September 26, 2026	Fergus	Industrial Building Construction	Worker	Worker suffered fractured arm after falling approx. 6ft from a ladder.
Fall – Same Level (7)					
1	September 5, 2026	Unorganized North Cochrane District	Excavation	Worker	Worker suffered fractured ankle while walking on uneven surface.
2	September 10, 2026	Toronto	Institutional Building Construction	Worker	Worker fractured his leg after falling while walking down a ramp.
3	September 16, 2026	Toronto	Commercial Building Construction	Electrician	Worker suffered fractured leg and ankle after tripping over cable.
4	September 16, 2026	Sault Ste. Marie	Industrial Building Construction	Installer	Worker suffered a fractured foot after tripping while walking backward.
5	September 25, 2026	North York	Industrial Building Construction	Labourer	Worker suffered a critical injury after falling down approx. 4 steps.
6	September 28, 2026	Sault Ste Marie	Industrial Building Construction	Rigger	Worker suffered fractured arm after a fall while walking.

	Date of Incident	**Municipality** (Where incident occurred)	**Sector** (Refer to Sector Description Table)	**Occupation** (Of Injured Person)	**Details** (As reported at the time of incident)
7	September 29, 2026	Tiverton	Industrial Building Construction	Worker	Worker fractured his ankle after slipping while walking.
Stuck By – Material (6)					
1	September 2, 2026	Mississauga	Apartment & Other Multiple Housing	Pipefitter	Worker suffered amputation of a finger after it was pinched between pipe and curb.
2	September 4, 2026	York	Single Family Housing	Labourer	Worker suffered critical injury after a granite slab fell on him.
3	September 14, 2026	Brampton	Industrial Building Construction	Installer	Worker suffered a fractured foot after the racking system being installed fell onto his foot.
4	September 15, 2026	Webequie	Bridge Construction	Electrician	Worker suffered fractured wrist after spool of wire contacted his wrist.
5	September 15, 2026	Waterloo	Apartment & Other Multiple Housing	Carpenter	Worker suffered fractured leg after a shelf fell on him during restoration.
6	September 23, 2026	Hamilton	Sewer / Watermain Construction	Rigger	Worker lost consciousness and life threatening back injury after being stuck by plywood that came loose while being lifted.
Fall - From Equipment (4)					
1	September 10, 2026	Milford	Single Family Housing	Scaffolder	Worker lost consciousness and suffered life threatening injury

	Date of Incident	**Municipality** (Where incident occurred)	**Sector** (Refer to Sector Description Table)	**Occupation** (Of Injured Person)	**Details** (As reported at the time of incident)
					after falling approx. 11ft from scaffold.
2	September 14, 2026	Ottawa	Institutional Building Construction	Worker	Worker suffered a fractured ankle after falling from the tailgate of his truck.
3	September 16, 2026	Milton	Commercial Building Construction	Painter	Worker suffered a critical injury (fracture) after falling approx. 6ft from a rolling scaffold as it was being moved.
4	September 18, 2026	Kingston	Single Family Housing	Mason	Worker suffered life threatening injuries after falling approx. 15ft from a scaffold.
Struck By - Equipment (2)					
1	September 1, 2026	Corbyville	Asphalt Paving	Paver	Worker suffered fractured foot after it was run over by a skid steer.
2	September 14, 2026	Timmins	Institutional Building Construction	Operator	Worker suffered amputation of multiple fingers after they were pinched while unloading an attachment for a skid steer.

Ministry of Labour, Immigration, Training and Skills Development

Occupational Health and Safety Branch - Construction Health and Safety Program

Sector Classification	Sub-Sector Description	Code
Residential	Apartment and Other Multiple Housing	RESM
	High Rise (10+ storeys)	RESM
	Low-Rise (less than 4 storeys)	RESM
	Medium Rise (4 to 9 storeys)	RESM
	Residential Construction	RESM
	Single Family Housing	RESS
ICI	Commercial Building Construction	COMM
	Industrial Building Construction	INDU
	Institutional Building Construction	INST
Underground	Caisson	CAIS
	Cofferdam	COFF
	Excavation	EXCA
	Pipeline	PIPE
	Sewer / Watermain	SEWW
	Shaft Construction	SHAF
	Subway	SUBW
	Trenching	TREN
	Tunnel	TUNN
	Well Drilling	WELL
Infrastructure	Asphalt Paving	PAVE
	Bridge Construction	BRID
	Excavation – Grading	GRAD
	Highway and Road Construction	ROAD
	Railway	RAIL
Power	Cable	CABL
	Electrical Towers and Transmission Lines	ETTL
	Gas Service Connection	GAS
	Hydro	HYDR
	Hydroelectric Power Plants	POWP
Diving	Construction	DCON
	Environmental	DENV
	Film and Television	DFTV
	Industrial	DIND
	Mining	DMIN
	Scientific	DSCI
Marine	Marine Construction	MARE
	Shipbuilding and Repair	SHIP
	Asbestos – Type I	ASB1
	Asbestos – Type II	ASB2
NEC – Construction	Asbestos – Type III	ASB3
	Mining Plant Construction	MINP
	Moving of a Building / Structure	MOVE
	Telephone	TELE
	Window Cleaning Services	WIND